

LA-UR-21-26898

Approved for public release; distribution is unlimited.

Title: State of HRL Facilities

Author(s): Hong-Geller, Elizabeth
Deshpande, Alina

Intended for: Documentation of aging HRL faciity

Issued: 2021-07-16

Disclaimer:

Los Alamos National Laboratory, an affirmative action/equal opportunity employer, is operated by Triad National Security, LLC for the National Nuclear Security Administration of U.S. Department of Energy under contract 89233218CNA000001. By approving this article, the publisher recognizes that the U.S. Government retains nonexclusive, royalty-free license to publish or reproduce the published form of this contribution, or to allow others to do so, for U.S. Government purposes. Los Alamos National Laboratory requests that the publisher identify this article as work performed under the auspices of the U.S. Department of Energy. Los Alamos National Laboratory strongly supports academic freedom and a researcher's right to publish; as an institution, however, the Laboratory does not endorse the viewpoint of a publication or guarantee its technical correctness.

State of HRL Facilities



HRL – Front door and steps

Back wall of HRL next to the dog runs





Rusty escape staircase



Damage to exterior facing – pests come in



Cracks in the cement block walls



Cracks and lifting up of staircase treads



Water leaks and ceiling tile damage throughout building



Peeling ceiling paint



Most of basement level closed down since HVACs not working



HVAC failures – Portable AC units venting into the ceiling to keep lab temps cool





Portable AC in COVID-19 Diagnostic Testing Lab to keep temps cool

Cracked floor tiles throughout building



Cracked ceiling tiles throughout building



Auditorium chairs old with worn fabric and broken desk trays



Windows hardware has failed requiring windows to remain closed

